

Parish Flood List

74 Next
Number

75

#	Location	Where	Landowner / Responsibility	Issue/Impact (Jan 16)	Cause	Short Term Actions (by Feb 16)	Maintenance Required	More Action Needed	Steps Already Taken (Oct 16 Update)
31	Grisedale	Braesteads Farm	Matson Ground Estate	Landslips beyond Eagle Cottage					Landslips examined - issue with rockbar. Consider tree planting to stabilise ground. Grisedale Beck and valley to be considered in pilot
32	Grisedale	Braesteads Farm	Matson Ground Estate	Blocked Field Drains					Drains cleared
33	Grisedale	Grisedale Beck	Patterdale Hall Estate	Kennel Bridge road scoured		Rebuild road surface			Road repaired.
34	Grisedale	Grisedale Beck close to Kennels	Patterdale Hall Estate	Landslip and trees in beck				Ongoing tree management in Patterdale Hall Estate and bank stabilisation strategy	Trees cleared and beck wall stabilised short term. More tree work needed in the autumn
35	Grisedale	Grisedale Beck above Close Cottage	Patterdale Hall Estate	Landslip and trees in beck - potential threat of road being undermined		Oak tree on bank to be pollarded from road side		Ongoing tree management in Patterdale Hall Estate and bank stabilisation strategy	Trees cleared and beck wall stabilised short term. Highways working on long term stabilisation measures
36	Grisedale	Grisedale Beck by caravan park	Patterdale Hall Estate	Major beck breach, with beck bank destruction and road surface destruction outside Patterdale Hall and flooding of properties in Patterdale	Volume of water and tree stumps being stored which tore up the road surface			Ongoing tree management in Patterdale Hall Estate and bank stabilisation strategy.	Beck dredging either side of the bridge and rebuilding of beck bank complete
37	Grisedale Bridge	Grisedale Bridge	Various	Grisedale Beck breach on both sides causing flooding of Grisedale Bridge properties, Mountain Rescue Base and Fire station	Volume of water and debris in the beck		Agree correct beck depth and dredge as required		Beck dredged and bank built up by Mountain Rescue base. Beck wall repairs on other side (Sept 16)

Parish Flood List

#	Location	Where	Landowner / Responsibility	Issue/Impact (Jan 16)	Cause	Short Term Actions (by Feb 16)	Maintenance Required	More Action Needed	Steps Already Taken (Oct 16 Update)
38	Grisedale Bridge	Church Flats Field	Various	Debris in fields, and water backing up causing secondary flooding to properties at Grisedale Bridge	Volume of water/debris in beck reducing capacity	Remove debris from side of beck - gravel and trees	Agree correct beck depth and dredge as required		Beck Dredged, fields cleared