Parish Flood List

74 Next 75 Number

#	Location	Where	Landowner /	Issue/Impact (Jan 16)	Cause	Short Term Actions	Maintenance	More Action Needed	Steps Already Taken (Oct
			Responsibility			(by Feb 16)	Required		16 Update)
14	Deepdale	Lane Foot	Various	Beck wall collapse,	Volume of water,	Remove trees from in	Agree correct	Rebuild beck wall and	Dredging of beck and
		Cottages and		gardens lost, houses	stone/gravel in beck	the beck on Manor	beck depth and	reinstate gardens	build up of banks to
		Deepdale		flooded	and trees in the beck	Barn side	dredge as		protect houses and
		Bridge			on the opposite bank		required.		gardens complete.
							Pollard trees		Further wall being built
15	Deepdale	Fields below	Deepdale Hall	Fences down and	Volume of water	Clear Gravel from			Fences reinstated
		Lanefoot		gravel in fields		fields			